

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: LUG
Job Number	: 36699		
Estimate Number	: 11696		
P.O. Number	:	Part Number	: D2713
This Issue	: 1/9/2008 S.O. No. :	Drawing Number	: D2713 REV A
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: 11 Type : MACHINED PARTS	Drawing Revision	: A
Previous Run	:	Material	:
Written By	: <u>18/08.01.09</u>	Due Date	: 02/15/2008 Qty: 40 Um: Each
Checked & Approved By	: <u>18/08.01.09</u>		
Comment	: Est:C 02.01.14 Added Tumble at step 5 NG/EC		

[illegible]

Batch 28323

J.L 08/03/10

[illegible]

J.L 08/03/10

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete each task.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress regularly to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves comparing the actual outcomes with the original objectives and goals to determine the effectiveness of the project.

J.L 08/03/14



J.L 08/03/14



08-03-17 10

\_\_\_\_\_

*M. L.*

08/03/17

40X

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes ☒ No ☐ DQA: LD Date: 08/03/19  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Corrective Action		Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng		Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/9/2008 3:42:15 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LUG

Job Number: 36699

Part Number: D2713

Job Number:



Seq. #:

Machine Or Operation:

Description :

7.0

POWDER COATING

POWDER COATING



M 107005



(40)

Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

BR 08-03-18

8.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



(40)

Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

FR 08/03/18

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: ST 480

AS 08/03/19

(40)

10.0

QC21

FINAL INSPECTION/W/O RELEASE



(40)

Comment: FINAL INSPECTION/W/O RELEASE

08/03/19

Job Completion



mi 2008/3/19

(40)

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_


NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Corrective Action		Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng		Sign & Date			

NOTE: Date & initial all entries



DESIGN KE	DRAWN BY KE	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED [Signature]	APPROVED [Signature]	DRAWING NO. D2713	REV. A SHEET 1 OF 1
DATE 38.04.01		TITLE BRACKET	SCALE 1:1
A	98.04.01	NEW ISSUE	

RELEASED  
98/04/20 KE



MATERIAL: MAKE FROM EXTRUSION D2761  
FINISH: ACID ETCH, ALODINE PER DART QSI 005 4.1  
POWDER COAT WHITE PER DART QSI 005 4.3  
TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

